

## STANDARD DRAWING E 609-RCBA

SHEET	DATE	BY	REVISION
01	09/04/12	ALU	Deleted. Information moved to IDM 17-5.0.
02	09/04/12	ALU	Renumbered, see 503-BATJ-01. Drawing format updated. Revised notes.
03	09/04/12	ALU	Deleted. Information moved to IDM 17-5.0.
04	09/04/12	ALU	Deleted. Information moved to IDM 17-5.0.
05	09/04/12	ALU	Deleted.
06	09/04/12	ALU	Deleted.
07	09/04/12	ALU	Renumbered, see 609-RCBA-01. Drawing format updated. Revised notes.
01	09/02/14	EWP	New drawing. Changed from previous 609-RCBA-03: replaced 491 and #4 bars with straight #5 bars, moved section and bar-bending diagram to Sheet -01, added notes 4 and 5, added Key. See also IDM Figures 17-5G(1) and 404-3H. Standards Committee Dec 2013.
02	09/02/14	EWP	New drawing. Changed from previous 609-RCBA-04: oriented transverse bars perpendicular to centerline, replaced 491 and #4 bars with straight #5 bars, moved section and bar-bending diagram to Sheet -01, added alternate bar configuration to top mat, added notes 5 and 6, added Key. Standards Committee Dec 2013.
03	09/02/14	EWP	Renumbered sheet from 609-RCBA-01, removed note 3, added new notes 3 and 4, added Key. Replaced 5905 (599E) bar with #5 threaded tie bar, replaced 491 and #4 bars with straight #5 bars, added section, revised bar-bending diagram. Removed callouts for specific backfill material (coarse aggregate #8 or 39), revised pavement ledge to 6" Min. Standards Committee Dec 2013.